



IMPORTING .LIA FILES INTO PCAD

1. Open PCADS Library Executive and from the Library menu select Translate
2. Select P-CAD ASCII as the Source Format and P-CAD Binary as the Destination Format then click the Source Library button.
3. Browse to and select the *.lia file you want to translate
4. Click the Open button
5. Click the Destination Library button and enter a name and path for the new library then click the Save In button
6. At the Library Translate dialog, click the Translate button

You can now use this file as a normal P-CAD library file.